

# 26 Bridgewater (Green Point ) STP

### 26.1 Activity and report details

Activity name	Bridgewater (Green Point) ST	Ρ	
Activity address	Eddington St, Bridgewater, He	obart	
Permit number	Licence to Operate – 3447	Date of issue	16/10/1989
EPN	8844/1 7058/2	Date of issue	5/03/2013 4/08/2020
Treatment level	Secondary Treatment		
Authorised Dry Weather Flows	3500 kL/day		
Key Influent Source	Residential/Industrial 1 x Category 3 Customer		
Contact person	Kate Westgate		
Report author	George Fitzgibbon		
Contact details	Environment@taswater.com	au	
Date of submission	30 September 2023		

Figure 26-1: Green Point Sewage Treatment Plant



Tasmanian Water & Sewerage Corporation Pty Ltd GPO Box 1393 Hobart, TAS 7001 ABN: 47 162 220 653 CM record number: 23/65055 Uncontrolled when printed Page 1 of 12



# 26.2 Monitoring and compliance summary

# 26.2.1 Flow data

#### Table 26-A: Flow monitoring summary

	Influent	Effluent	Reuse
Location Name	Inlet	Derwent River	Brighton Recycled Water Scheme
Coordinates	E 519522 N 5267820	E 519482 N 5267582	E 519574 N 5267757
Method of Measurement	Level sensor	Level sensor	Level sensor
Date of last Calibration/Validation (if applicable).	30/03/2023	30/03/2023	30/03/2023

#### Table 26-B: Annual flow and rainfall data

Month	Average Daily Influent Volume (kL/day)	Rainfall (mm/month) BOM Station ID 94258	Discharge to Waters Total Effluent Volume (ML)	Discharge to Reuse Total Effluent Volume (ML)
July 2022	2,255	19.2	67.43	2.43
August 2022	2,855	84.4	85.99	1.35
September 2022	3,374	46.4	101.23	0.00
October 2022	3,840	80.2	119.03	0.00
November 2022	3,461	52.0	93.22	5.68
December 2022	3,230	46.6	103.35	0.00
January 2023	2,532	6.0	34.05	51.20
February 2023	2,342	39.4	0.00	72.42
March 2023	2,362	35.8	13.78	61.35
April 2023	2,387	22.8	0.00	75.78
May 2023	2,351	26.4	20.38	55.43
June 2023	2,448	60.6	1.47	75.92
Annual 2022-23	2,789	519.8	639.92	401.58
% of Total Discharge			61.4%	38.6%

2022-23 monthly flow data was submitted directly to the EPA.



#### 26.2.2 Bypass events

There were 9 bypass events associated with the STP during the reporting period.

#### Table 26-C: Bypass events summary

Bypass ID:	GRPST01-OPSD				
Bypass description:	Trickling Filter Recirculation P	it overflow to the Ch	lorine Contact Tank		
Treatment bypassed:	Secondary Treatment (Activa	ted Sludge)			
Treatment level of impacted effluent:	Screened, De-gritted, Primary	rreated, Secondary	Treated (Trickling Filt	er), and Disinfected (Chlorine)	
Flows exceeding:	110 L/s (Approximate)				
Discharge location:	River Derwent: 519539E, 526	7705N (GDA94)			
Start date / time	End date / time	Duration	Volume estimate	Cause	Response actions
14/08/22 04:30	16/08/22 00:22	43.9 h	209 kL	Rainfall Event	No specific actions undertaken
16/08/22 07:33	16/08/22 09:47	2.2 h	4 kL	Rainfall Event	No specific actions undertaken
16/09/22 19:23	16/09/22 21:45	2.4 h	8 kL	Rainfall Event	No specific actions undertaken
22/10/22 12:13	22/10/22 14:41	2.5 h	11 kL	Rainfall Event	No specific actions undertaken
26/10/22 10:36	29/10/22 12:56	74.3 h	311 kL	Rainfall Event	No specific actions undertaken
11/12/22 21:12	11/12/22 23:52	2.7 h	12 kL	Rainfall Event	No specific actions undertaken
13/12/22 20:04	14/12/22 00:58	4.9 h	23 kL	Rainfall Event	No specific actions undertaken
16/01/23 07:13	16/01/23 10:18	3.1 h	12 kL	Rainfall Event	No specific actions undertaken
01/05/23 09:47	01/05/23 14:03	4.3 h	20 kL	Rainfall Event	No specific actions undertaken



# 26.3 Discharge compliance with permit limits

#### Table 26-D: Compliance Summary

Parameter	Ammonia	BOD5	Chlorine	Nitrogen	Oil and grease	рН	Phosphorous	E coli	Total suspended solids
Permit/EPN limit	mg/L	mg/L	mg/L	mg/L	mg/L	Units	mg/L	MPN/100ml	mg/L
Maximum	30	30	1.0	45	10	8.5	10	200	30
90th percentile									
50th Percentile									
Minimum						6.5			
Samples analysed									
Number required	12	12	12	12	12	12	12	12	12
Number analysed	12	12	12	12	12	12	12	12	12
Statistical summary									
Max	43.8	72	1.03	60.5	5.0	7.5	9.4	24196	23.8
90th percentile	41.3	62	0.91	58.4	4.3	7.3	9.3	23043	20.3
50th percentile	29.9	26	0.74	56.4	2.0	6.9	8.1	442	14.7
Min	12.5	7	0.29	38.0	1.6	6.4	5.8	10	7.8
EPN Limit Compliance									
% compliance with Maximum	50%	58%	92%	8%	100%		100%	25%	100%
% compliance with 90th percentile									
% compliance with 50th percentile									
% compliance with pH range						83%			

Tasmanian Water & Sewerage Corporation Pty Ltd GPO Box 1393 Hobart, TAS 7001 ABN: 47 162 220 653 CM record number: 23/65055 Uncontrolled when printed Page 4 of 12



#### Table 26-E: Mass loads to the environment

Parameter	EPN Limit	Frequency	2022-23 result
Nitrogen (kg)	7884	Annual	34397.8
Phosphorous (kg)	1752	Annual	5145.3
Method	Flow weighted/Co	omposite method	

#### Table 26-F: Performance Analysis (Discharge to environment)

Effluent compliance parameter	Date(s) of non-compliance		Reasons for non-compliance	Actions to improve performance
E. coli	12/07/2022 09/08/2022 13/09/2022 11/10/2022	06/12/2022 10/01/2023 14/03/2023 13/06/2023	Instances of elevated E. coli typically correspond with lower effluent chlorine concentrations caused by limited control automation. The variability in effluent quality from the secondary treatment process is also believed to impact the consistency disinfection	Minor improvements to the chlorine dose rate control.
Chlorine	9/05/2023		performance. Failure of high chlorine is a result of the limited automated control in the dosing system.	
BOD	13/09/2022 10/11/2022 06/12/2022 10/01/2023		The reason for the non-compliances is not known but correlate with periods of higher total suspended soilds.	Investigations to understand reasons for non-compliances.
Nitrogen	12/07/2022 13/09/2022 10/11/2022 06/12/2022	10/01/2023 14/03/2023 9/05/2023 13/06/2023	The plant is a trickling filter process, not designed to remove nitrogen or ammonia.	No specific actions undertaken.



Effluent compliance parameter	Date(s) of non-o	compliance	Reasons for non-compliance	Actions to improve performance
Ammonia	12/07/2022 13/09/2022 10/11/2022	10/01/2023 9/05/2023		
рН	9/08/2022 13/06/2023		Possible alkalinity consumption from increased nitrification causing low pH in effluent as these test results correlate with lower effluent ammonia concentrations. There is no pH correction installed at the treatment plant.	No specific actions undertaken.

Note: Non-compliances only identified for the times STP has discharged to water

No other parameters had exceedances in the reporting period.



### 26.4 Reuse Annual Reporting

The Green Point and Brighton STP's supply recycled water for irrigation purposes to twelve properties across the Bridgwater area. One property (Rosewood subdivision) commenced recycle water irrigation during 2021-22.

Parameter	BOD5	рН	E coli
Permit/EPN limit	mg/L	Units	MPN/100ml
Maximum	50	9.0	10000
90th percentile			
50th Percentile			1000
Minimum		5.5	
Samples analysed			
Number required	12	12	12
Number analysed	12	12	12
Statistical summary			
Max	72	7.5	24196
90th percentile	62	7.3	23043
50th percentile	26	6.9	442
Min	7	6.4	10
Summary of results			
% compliance with Maximum	83%		75%
% compliance with 90th percentile			
% compliance with 50th percentile			58%
% compliance with pH range		100%	

Table 26-G: Reuse Compliance Summary

### Table 26-H: Performance analysis (Discharge to reuse)

Reuse Compliance Parameter	Date(s) of non- compliance	Reasons for non-compliance	Actions to improve performance
BOD	10/11/2022 10/01/2023	See Table 26F	See Table 26F
E. coli	09/08/2022 14/02/2023	See Table 26F	See Table 26F

Note: Non-compliances only identified for the times STP has discharged to reuse

Annual soil sampling was completed at nineteen sites on eleven properties across the Brighton RWS in late June, July and August 2022. The distribution of the sampling sites was based on the established sampling program and consideration of the irrigation application rates for the past irrigation and proposed coming irrigation season. As such, two new sampling sites (BRI CRE 05 and



BRI KEL 01) were included into the program, with four sites (BRI BER 01, BRI CRE 04, BRI GLE 01 and BRI THR 02) were removed. Annual compliance audits were completed at twelve properties in July and August 2022. Mostly completed by phone, field observations were conducted in conjunction with the soil sampling. Annual sampling of the nine privately owned customer recycled water storage dams supplied by the scheme was completed in October 2022. This sampling was completed as part of the annual sampling program implemented in 2016, on direction from the EPA. A summary of the findings of the programs is provided in the below table.

Program	Compliance audit	Soil monitoring	Dam sampling
Compliance status	Two properties fully compliant. Main non-compliance: inadequate signage on property entrance, boundaries and taps. <u>Major non-compliances:</u> Strathallan: Inadequate fencing around storages (ongoing non-compliance issue). Livestock located within a recycled water storage dam boundary. Cremorne: No IEMP	Average ECse and Cl levels fluctuate between years, ranging from non-saline to low-level saline. No long- term trend. Levels in 2022 are slightly higher than the previous year. Average ESP levels fluctuate between years, ranging from non-sodic to borderline sodic. No long- term trend. ESP level remain similar to 2020 and 2021. Average P level is excessive, average K is high and average S level is moderate. Increasing long- term trend in average P and K. P increasing at a slower rate than K. Average P and K levels remain slightly below 2019 peak. No long-term trend in average S.	Recycled water quality in all customer dams (at 12 October 2022) was compliant with class B recycled water standards All other water quality indicators generally satisfactory. Soil sodicity indicators were acceptable and suited to irrigation. Nutrient concentrations typical of recycled water.
Comments	Aspects of original Site Management Plans are outdated for numerous properties. TasWater will be looking to review the current Brighton EMP during the 2023-24 reporting period and work with customers to address updating customer IEMPs following EMP review. Strathallan have been advised of fencing requirements of storages.	Overall soil health and fertility do not appear to be adversely impacted through recycled water irrigation. Review of recycled water quality indicates a very slight risk of soil permeability loss resulting from application of recycled water. Therefore, considered highly unlikely future sodicity issues will develop due to application of recycled water schemes. Long-term average P and K trend levels have stabilised and trend correlates with sources other than recycled water application. Average levels are strongly influenced by excessive	Throughout the reporting period additional sampling was completed at customer dams as part of the customer risk management and notification framework for elevated exceedances of <i>E.Coli</i> from the Scheme. The October 2022 dam review highlighted this framework continues to be an effective means of managing risk to customers associated with recycled water quality.

Table 26-I: Annual recycled water scheme compliance audit and soil monitoring report summary

Tasmanian Water & Sewerage Corporation Pty Ltd GPO Box 1393 Hobart, TAS 7001 ABN: 47 162 220 653 CM record number: 23/65055 Uncontrolled when printed Page 8 of 12

· · · ·
<b>Taswater</b>

Key: K= Potassium; P=Phosphorous; S = Sulphur; SAR=Sodium Absorption Ratio, ECse=Electrical conductivity at saturation extent; Cl=Chloride; ESP=Exchangeable sodium percentage.

The Brighton RWS groundwater monitoring network consists of ten monitoring bores located across eight properties. Five bores (BR-THGW1, BR-HWGW3, BR-STGW1, BR-STGW3 and BR-RIGW1) are associated with recycle water storage dams. Biannual sampling was completed at nine bores in August 2022. Due to time and resource constraints three bores (higher risk bores) were sampled during the annual sampling round in April 2023.

levels at a few sites where known nutrient inputs are

significant.

Three properties identified moderate issues that are considered unlikely to be linked to recycled water use. No evidence of impact of groundwater quality found at three properties. One property identified a significant issue (elevated total nitrogen concentrations above guideline criteria) although slight decrease in levels over last three groundwater monitoring events. All other properties recorded no or minor issues.

Two bores (BR-ROGW3 and BR-HWGW3) require repair and maintenance work or replacement. TasWater will review its maintenance requirements across the state in 2023-24.

Biannual sampling will continue at all bores during the 2023-24 groundwater monitoring program. Three bores (bore ID #'s BRGW-Manton, BR-GQGW1 and BR-RIGW1) will be sampled at the extended analytical suite to investigate identified. Private recycled water storage associated with BR-GQGW1) will be sampled so that chemical characterisation can be completed. As per previous report total alkalinity will be included in the standard sampling suite across the groundwater sampling program.

Table 26-J: Program details				
Program	NA – No requirement for ambient monitoring in the reporting period			
Status	ΝΑ			
Update	ΝΑ			
Comments	ΝΑ			

# 26.5 Ambient monitoring program

### 26.6 Groundwater monitoring

A groundwater monitoring plan (GMP) was developed in February 2020 and submitted to the EPA in April 2021 as per condition G8 of the EPN. The GMP recommended the under-liner drainage system, located underneath the recycled water storage lagoon (RSL) HDPE liner, be considered as the groundwater contamination monitoring location. Further investigations of the under-liner drainage system confirmed the proposed as a suitable monitoring location and recommended conducting quarterly sub-liner groundwater and RWS lagoon monitoring events for one year. First review of a full set of quarterly monitoring was completed in June 2023.

Report concluded nutrient analysis results suggest the groundwater and RWS Lagoon nutrient levels remain relatively consistent and distinctly different (exception in November 2022 sampling event). In addition bacteriological results have been significantly different. Report also found



hydrogeochemical assessment of sub-liner groundwater and RWS Lagoon results suggested August and November 2022 samples somewhat similar, however if liner leakage was occurring then elevated principle contaminants of concern nutrients and bacteriological parameters would be expected in sub-liner groundwater samples which was not the case.

Quarterly sampling at both will continue during the 2023-24 monitoring program, and a review of methodology as per report recommendations will occur during 2023-24 reporting period.

# 26.7 Inflow and infiltration (I&I)

The latest revision to the TasWater Inflow and Infiltration Management Plan includes details of the actions undertaken statewide to address I&I issues. Update to the actions completed will be provided in the next revision due September 2024.

A Multi Criteria Assessment was undertaken by TasWater in 2022 to prioritise I&I investigation and works state-wide. This catchment was ranked 77 out of 79 in priority.

### 26.8 Sludge and Biosolids

The latest revision to the Sewage Sludge Management Plan (SSMP) includes full details of the actions undertaken during the reporting period, the most recent sludge profiling results, and upcoming annual desludging program.

This STP is fully compliant with the 2022-23 SSMP.

Biosolids are removed regularly from site, no stockpiling occurs.

Month	Number of Samples	Maximum (mg/kg)	Mean (mg/kg)	Minimum (mg/kg)	BACC (mg/kg)	Contaminant Classification
Arsenic	12	3.0	2.5	1.7	3.3	A
Cadmium	12	3.7	3.0	2.4	3.8	В
Chromium	12	38.4	28.1	17.7	43.2	A
Copper	12	462.0	315.4	261	419.7	В
Lead	12	39.4	29.3	22.8	39.9	A
Mercury	12	0.8	0.5	0.06	0.8	A
Nickel	12	26.1	20.7	14	29.4	A
Zinc	12	1410.0	1113.6	928	1383.5	В

#### Table 26-K : Biosolids sludge classification summary

#### Table 26-L: Volume and disposal destination

Quantity (DST)	Average solids content	Stabilisation method	Stabilisation Grade	Contamination Grade	Biosolids Classification	End use destination
66.19	19.0%	Anaerobic digestion	В	В	2	Richmond Farm. Coronation Hotel- Runnymede. Delmore Farm. Flexmore Park Farm.
1.26	19.0%	Anaerobic digestion	В	U/C	U/C	Dulverton Compost

Notes: DST = Dry solid tonne. U/C = Unclassified



### 26.9 Non-compliance with other permit requirements

EPN Condition	Description of non-conformance	Future Actions to be taken
M6 Event Recorder for Bypass	No flow meter currently in place	Flow meter in program to be installed
OP2 Operational Procedures Manual	No contemporary Operational Procedures Manual	New SharePoint based solution for OPMMs currently being developed. First version to be implemented in FY24
EM4 Discharge Management Plan	Discharge Management Plan overdue.	Submission timeframe TBC. Plan in development for DMP submission dates following on from agreed format between TasWater and EPA
EF2 Effluent quality limits for discharge to water	Discharge compliance with permit limits	See section 26.3 Discharge compliance with permit limits and Performance Analysis
EF3 Effluent quality limits for discharge to a reuse scheme	Discharge compliance with reuse permit limits	See section 26.4 Reuse Annual Reporting and Performance Analysis
EF7 Mass Loads	Non-compliant for Nitrogen and Phosphorus mass loads based on loads	Investigate ways to increase recycled water usage
M3 Groundwater Monitoring	Groundwater Monitoring not as per specific requirements	Improve monitoring program for FY23/24 to meet compliance

Table 26-M: EPN non-compliances

# 26.10 Complaints and incident reporting

Table 27-N: Complaints Reporting

Date	Category	Details	Mitigation actions
31/08/2022	Odour	Strong sewer odour coming from STP	Investigation occurred and rectified. Contact made with customer.

#### Table 26-O: Incident Reporting

Date	Category	Details	Mitigation Actions
28/04/2023	Mechanical	Trickling filter had a mechanical failure (arms not rotating). Potential for the process to be upset as there may be some solids carry over due to reduced treatment efficiency to break down the organic matter in the wastewater.	Fixed on 1 May 2023. Going to reuse the entire period.
19/08/2023	Mechanical	No disinfection at the STP due to an effluent pump issue. Effluent being	Full chlorination back online

		<b>řaswaře</b>	ľ
	discharged to the Derwent. Approximately 200kL.	The effluent line failure that caused the issue was rectified.	

### 26.11 Any other relevant information

Table 26-P: Projects or significant operational events that occurred in FY 2022-23:

Project or significant operational event	Progress
Planning stages for biosolids management upgrade	Planning phase

# For further information on Green Point STP please contact TasWater on 13 6992

www.taswater.com.au